1-00434	BD FUEL INJECT	7/19/2019	
Model	Full Credit Criteria	Deduction	No Credit
P7100 Injection Pump	 Like for Like, application years & models must match. No external damage All components present and assembled. 	 Governor Housing Damaged Front or Back (25% Deduction) Main Body Damaged (50% Deduction) AFC Housing Damaged (25% Deduction) Cracked or Damaged due to freight (50-100%) 	 Fire Damage Contaminated/Bio Diesel Excessive Rust or water damage Damaged Camshaft on 911/913 pumps. Part disassembled
Bosch VE Pump	 Like for like No Fire Damage All components present and assembled. No external damage 	 Missing Parts (50% Deduction) AFC Housing Damaged (25% Deduction) Main Body Damaged (50% Deduction) Cold Advanced Housing Damaged (50% Deduction) 	 Fire Damage Contaminated/Bio Diesel Excessive Rust or water damage Seized Head (Does not turn) Part disassembled
CP3	 Like for Like No Housing Damage All components present and assembled. 	Missing/Damaged Metering Unit (50% Deduction)	 Fire Damage Contaminated/Bio Diesel Excessive Rust or water damage Seized (Does not turn) Part disassembled
High Performance CP3	 No Housing Damage All components present and assembled. 	Missing Metering Unit (50% Deduction)	 Fire Damage Contaminated/Bio Diesel Excessive Rust or water damage Seized (Does not turn) Part disassembled
VP44	 All components present and assembled. Like for like models Must be rebuildable 	 Missing or Damaged Electronics (50% Deduction) Seized Head (Does not turn) (50% Deduction) 	 Fire Damage Contaminated/Bio Diesel Excessive Rust or water damage Damaged Housing Part disassembled
High Performance VP44	All components present and assembled.Must be rebuildable	 Missing or Damaged Electronics (50% Deduction) Seized Head (Does not turn) (50% Deduction) 	 Fire Damage Contaminated/Bio Diesel Excessive Rust or water damage Damaged Housing Part disassembled
Common Rail Injectors	 All components present and assembled. Like for like models Body and threads are in good quality Solenoid Broken plastic tabs allowed. 	Solenoid melted or destroyed beyond repair (25% Deduction)	 Fire Damage Contaminated/Bio Diesel Excessive Rust or water damage Damaged Body Part disassembled
Mechanical Injectors	Like for like Body and threads are in good quality Freight and Removal of	damage are not covered. Ensure you packaged the co	Fire Damage Contaminated/Bio Diesel Excessive Rust or water damage Damaged Body Part disassembled re sufficiently!

	BD TURBOCHARGER	CORE ACCEPTANCE POLICY	
Turbo Model/ Application	Full Credit Criteria	Deduction	No Credit
Cummins ISX VGT Air or Electronic Actuated	 Light or minimal damaged to Compressor & Turbine Wheel. Light or minimal damage to compressor and turbine housing. All components present and assembled. Like for like models 	 Missing Parts or Actuators (50% Deduction) Damaged Electronics (50% Deduction) Missing Clamps (25% Deduction) Heavily damage wheels and/or shaft (50% Deduction) Turbine Wheel Separation (50% Deduction) Cracked or Damaged due to freight (50-100%) Damaged Electronics (50% Deduction) 	Fire Damage Knock Off Models (Not Genuine) Excessive Rust or water damage
Caterpillar (Ball Bearing) Models	 Light or minimal damaged to Compressor & Turbine Wheel. Light or minimal damage to compressor and turbine housing. All components present and assembled. Like for like models, must have CAT logo 	 Missing Parts or Actuators (50% Deduction) Missing Clamps (25% Deduction) Heavily damage wheels and/or shaft (50% Deduction) Turbine Wheel Separation (50% Deduction) Cracked or Damaged due to freight (50-100%) Damaged Electronics (50% Deduction) 	 Fire Damage Knock Off Models (Not Genuine) Excessive Rust or water damage
Caterpillar (Standard Turbocharger) 704604-9007, 704604-9011)	 Light or minimal damaged to Compressor & Turbine Wheel. Light or minimal damage to compressor and turbine housing. All components present and assembled. Like for like, must have CAT or Garrett logo. 4 Support Webs 	 Missing Parts or Actuators (50% Deduction) Missing Clamps (25% Deduction) Heavily damage wheels and/or shaft (50% Deduction) Turbine Wheel Separation (50% Deduction) Cracked or Damaged due to freight (50-100%) Damaged Electronics (50% Deduction) 	 Fire Damage Knock Off Models (Not Genuine) Excessive Rust or water damage Turbo with 3 support Webs
Detroit Diesel VGT	 Light or minimal damaged to Compressor & Turbine Wheel. Light or minimal damage to compressor and turbine housing. All components present and assembled. Like for like models 	 Missing Parts or Actuators (50% Deduction) Missing Clamps (25% Deduction) Heavily damage wheels and/or shaft (50% Deduction) Turbine Wheel Separation (50% Deduction) Cracked or Damaged due to freight (50-100%) Damaged Electronics (50% Deduction) 	 Fire Damage Knock Off Models (Not Genuine) Excessive Rust or water

•	compressor and turbine housing. • All components present and assembled. • Like for like models	 Damaged VGT cage due to turbine wheel explosion (50%) Cracked or Damaged due to freight (50-100%) Damaged Electronics (50% Deduction) 	Excessive Rust or water
Dodge Cummins 6.7 HE351VG/HE300VG	 Light or minimal damaged to Compressor & Turbine Wheel. Light or minimal damage to compressor and turbine housing. All components present and assembled. Like for like models 	 Missing Parts or Actuators (50% Deduction) Missing Clamps (25% Deduction) Cracked or Damaged due to freight (50-100%) Damaged Electronics (50% Deduction) 	 Fire Damage Knock Off Models (Not Genuine) Excessive Rust or water
Standard Turbochargers (All Models, Non VGT)	 On Vehicle damaged to Compressor & Turbine Wheel. On Vehicle damage to compressor and turbine housing. All components present and assembled. Like for like models 	 Missing Parts or Actuators (50% Deduction) Damaged Electronics (50% Deduction) Missing Clamps (25% Deduction) Cracked or Damaged due to freight (50-100%) Damaged Electronics (50% Deduction) not covered. Ensure you packaged the core support to the core of the core	 Fire Damage Knock Off Models (Not Genuine) Excessive Rust or water

	BD TRANSMISSION ACCE		
Model	Full Credit Criteria	Deduction	No Credit
Transmissions	 No external damage No case cracks Drive shafts intact Dowel pin holes not damaged Threads not damaged No missing pieces Like for Like Must be assembled 	 Cracked or heavily corroded extension/OD housings (50% Deduction) Broken shafts (Requires disassembly for accurate costing) Missing electronics (25% Deduction) 	 Catastrophic damaged Damaged input shaft area, destroyed pump, case and convertor area Cracked Case Fire Excessive corrosion
Torque Convertors	 No Rust No damage to Hub, Impeller and turbine Like for like 	 Hub and Impeller damaged. (50% Deduction) Modified/Aftermarket convertors in which the stator or turbine have been modified. (Only on purchased cores. 50% Deduction) 	Excessive corrosionSeizedCatastrophic failure
Valve Bodies	Like for likeNo missing parts	Missing electronics (25% Deduction)	Excessive corrosion

GENERAL CORE ACCEPTANCE POLICY

Freight and removal damage are not covered. Ensure you packaged the core sufficiently!

Core must be rebuildable!